

## EAST Search History

### EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	11399	((717/168-178) OR (701/1,36)).CCLS.	US-PGPUB; USPAT	ADJ	ON	2010/11/06 17:00
L3	3	L2 and (software same installation same upgrade same USB)	US-PGPUB; USPAT	ADJ	ON	2010/11/06 17:01
L4	107	L2 and usb and download and history	US-PGPUB; USPAT	ADJ	ON	2010/11/06 17:01
L5	1	L2 and (software same installation same upgrade) and (portable flash)	US-PGPUB; USPAT	ADJ	ON	2010/11/06 17:01
L6	2	L2 and (usb same (portable or removable) near1 flash near3 card)	US-PGPUB; USPAT	ADJ	ON	2010/11/06 17:02
L7	1765	(software near2 manag\$5) and (vehicle\$1 or automobile \$1) and diagnostic and software	US-PGPUB; USPAT	ADJ	ON	2010/11/06 17:04
L8	7	((software near2 manag\$5) and (vehicle\$1 or automobile \$1) and diagnostic and software).CLM.	US-PGPUB; USPAT	ADJ	ON	2010/11/06 17:04

S1	2322	(717/168-178).ccls. and (@ad<"20031104" or @prad<"20031104" or @rlad<"20031104")	US-PGPUB; USPAT	ADJ	ON	2006/10/25 11:32
S2	0	S1 and (software same installation same upgrade same USB)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:50
S3	179	S1 and (software same installation same upgrade)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:52
S4	24	S3 and usb	US-PGPUB; USPAT	ADJ	ON	2006/10/19 10:55
S5	1	S3 and usb and download and history	US-PGPUB; USPAT	ADJ	ON	2006/10/19 10:55
S6	0	S3 and (open port) and processor	US-PGPUB; USPAT	ADJ	ON	2006/10/19 11:09
S7	0	S3 and (open port)	US-PGPUB; USPAT	ADJ	ON	2006/10/19 11:09
S8	0	S3 and (open near1 port)	US-PGPUB; USPAT	ADJ	ON	2006/10/19 11:09
S9	48	S3 and port	US-PGPUB; USPAT	ADJ	ON	2006/10/19 11:10
S10	24	S3 and usb	US-PGPUB; USPAT	ADJ	ON	2006/10/19 13:20
S11	0	"09120594"	US-PGPUB; USPAT	ADJ	ON	2006/10/19 13:20
S12	1	("6282469").PN.	US-PGPUB; USPAT	OR	OFF	2006/10/19 13:24

S13	29	"5916287"	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:43
S14	10	"5760938"	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:43
S15	2327	(717/168-178).ccls. and (@ad<"20031104" or @prad<"20031104" or @rlad<"20031104")	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:50
S16	0	S15 and (software same installation same upgrade same USB) and (vehicle or automobile)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:51
S17	0	S15 and (software same installation same upgrade same USB) and (vehicle or automobile or automotive)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:52
S18	0	S15 and (software same installation same upgrade same USB)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 08:52
S19	6	S15 and (software same installation same upgrade) and (car or automobile or automotive)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 09:47
S20	56	S15 and (software same installation same upgrade) and flash	US-PGPUB; USPAT	ADJ	ON	2006/10/24 09:57

S21	0	S15 and (software same installation same upgrade) and (portable flash)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 09:47
S22	0	S15 and (software same installation same upgrade) and (flash same USB)	US-PGPUB; USPAT	ADJ	ON	2006/10/24 09:51
S23	36	S15 and (software same installation same upgrade) and portable	US-PGPUB; USPAT	ADJ	ON	2006/10/24 09:57
S24	16	S15 and (software same installation same upgrade) and portable and flash	US-PGPUB; USPAT	ADJ	ON	2006/10/24 09:58
S25	0	S15 and (software same installation same upgrade) and portable near2 flash	US-PGPUB; USPAT	ADJ	ON	2006/10/24 09:58
S26	5	S15 and (software same installation same upgrade) and portable same flash	US-PGPUB; USPAT	ADJ	ON	2006/10/24 11:18
S27	17	S15 and (software same installation same upgrade) and removable same flash	US-PGPUB; USPAT	ADJ	ON	2006/10/24 11:20
S28	1	S15 and (software same installation same upgrade) and removable near3 flash	US-PGPUB; USPAT	ADJ	ON	2006/10/24 13:32
S29	1	"10710143"	US-PGPUB; USPAT	ADJ	ON	2006/10/24 13:33
S30	1	"20050097541"	US-PGPUB; USPAT	ADJ	ON	2006/10/25 11:31

S31	108936	"L1"	US-PGPUB; USPAT	ADJ	ON	2006/10/25 11:32
S32	2327	(717/168-178).ccls. and (@ad<"20031104" or @prad<"20031104" or @rlad<"20031104")	US-PGPUB; USPAT	ADJ	ON	2006/10/25 13:21
S33	2327	S32	US-PGPUB; USPAT	ADJ	ON	2006/10/25 11:32
S34	0	S32 and (usb same (portable or removable) near1 flash near3 card)	US-PGPUB; USPAT	ADJ	ON	2006/10/25 11:34
S35	4	S32 and (usb same (portable or removable) near3 card)	US-PGPUB; USPAT	ADJ	ON	2006/10/25 11:34
S36	4737224	(@ad<"20031104" or @prad<"20031104" or @rlad<"20031104")	US-PGPUB; USPAT	ADJ	ON	2006/10/25 13:21
S37	380	S36 and (removable or portable) same USB same flash same card	US-PGPUB; USPAT	ADJ	ON	2006/10/25 13:22
S38	9	S37 and (software near1 installation)	US-PGPUB; USPAT	ADJ	ON	2006/10/25 13:22
S39	0	20050102665a1	US-PGPUB; USPAT	ADJ	ON	2006/10/27 13:45
S40	0	("20050102665a1").PN.	US-PGPUB; USPAT	OR	OFF	2006/10/27 13:45
S41	1	("20050102665").PN.	US-PGPUB; USPAT	OR	OFF	2006/10/27 14:28

S42	1	("20050102666").PN.	US_PGPUB; USPAT	OR	OFF	2006/10/27 14:28
S44	421	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/01/26 22:01
S45	28	S44 and diagnostic and port \$1 and USB and software	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/01/26 22:20
S46	1	"20030163587".PN.	US_PGPUB	ADJ	ON	2008/01/26 22:08
S47	1	"20020035429".PN.	US_PGPUB	ADJ	ON	2008/01/26 22:08
S48	1	"6882712".PN.	USPAT; USOCR	ADJ	ON	2008/01/26 22:09
S49	2	("6687587").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/26 22:21

S50	2	("6370449").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/26 22:23
S51	2	("20030163587").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/26 22:34
S52	2	("6832141").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/26 22:40
S53	2	("6978198").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/26 22:48

S54	2	("7272475").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/26 22:44
S55	2	("20060271255").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/26 22:57
S56	2	("20060271255").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/27 14:31
S57	2	("6978198").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/27 14:31
S58	1	"20030163587".PN.	US_PGPUB	ADJ	ON	2008/01/27 14:32
S59	1	"20020035429".PN.	US_PGPUB	ADJ	ON	2008/01/27 14:39

S60	2	("7272475").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/27 14:40
S61	2	("6978198").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/27 14:40
S62	1	"20030163587".PN.	US_PGPUB	ADJ	ON	2008/01/27 14:40
S63	1	"20030163587".PN.	US_PGPUB	ADJ	ON	2008/01/27 14:41
S64	134	(automotive or vehicle) same (usb near3 device)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/01/30 08:48
S65	4	(automotive or vehicle) same (usb near3 device) same update\$1	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/01/30 08:52

S66	2	("6807469").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/01/30 08:53
S67	4	(Holland-Steven-W\$.IN.)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/10/26 10:06
S68	1	(Holland-Steven-W\$.IN.) and USB	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/10/26 10:07
S69	69	(vehicle software) same update \$3	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/10/26 10:14

S70	0	(vehicle software) same updat \$3 same USB	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/10/26 10:14
S71	4	((vehicle software) same updat\$3) and USB	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/10/26 10:15
S72	5	((vehicle or car or automobile) software) same updat\$3) and USB	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/10/26 10:19
S73	3	((vehicle or car or automobile) software) same updat\$3) and USB and diagnostic	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/10/26 10:21

S74	2	("20030060953").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/10/26 10:29
S75	4	(Holland-Steven-W\$.IN.)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/10 17:13
S76	2	("20070050105").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/11/10 17:17
S77	7939	vehicle with (software or driver\$1) with install\$\$5	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:46

S78	327	vehicle with (software or driver\$1) with install\$\$5 with (status or result\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:47
S79	81	(vehicle near1 (software or driver\$1)) with install\$\$5 with (status or result\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:47
S80	22	((vehicle near1 (software or driver\$1)) near3 install\$\$5) with (status or result\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:48
S81	0	((vehicle near1 (software or firmware\$1)) near3 install\$\$5) with (status or result\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:51

S82	0	((vehicle near1 (software or firmware\$1)) wiht install\$\$5) with (status or result\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:51
S83	0	((vehicle with (software or firmware\$1)) wiht install\$\$5) with (status or result\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:51
S84	0	((vehicle with (software or firmware\$1)) wiht install\$\$5)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:54
S85	3	(Knight-Alexander-N\$.IN.)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/11/11 15:56
S86	10	(vehicle software) same install \$5 same updat\$3	US_PGPUB; USPAT	ADJ	ON	2008/11/13 15:03
S87	10	(vehicle software) same install \$5 same (result or status)	US_PGPUB; USPAT	ADJ	ON	2008/11/13 15:08

S88	7	(vehicle software) same install \$5 same upgrad\$3	US-PGPUB; USPAT	ADJ	ON	2008/11/13 15:12
S89	0	(automobile software) same install\$5 same upgrad\$3	US-PGPUB; USPAT	ADJ	ON	2008/11/13 15:12
S90	0	(car software) same install\$5 same upgrad\$3	US-PGPUB; USPAT	ADJ	ON	2008/11/13 15:12
S91	7	(vehicle software) same install \$5 same upgrad\$3	US-PGPUB; USPAT	ADJ	ON	2008/11/13 15:13
S92	2	("6978198").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/11/13 15:14
S93	22	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 09:38
S94	22	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3)) and bus\$2	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 09:42

S95	22	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3)) and bus\$2 and interfac \$3	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 09:43
S96	22	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3)) and bus\$2 and interfac \$3 and (software or firmware) and processor\$1	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 09:43
S97	17	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3)) and bus\$2 and interfac \$3 and (software or firmware) and processor\$1 and diagnostic	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 09:45
S98	20	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and diagnostic	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 09:46

S99	14	(multiple near3 processor\$1 same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic same (result\$1 or report\$3))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 09:49
S100	2	("6687587").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/05/03 09:54
S101	2	("20030120395").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/05/03 09:55
S102	2	("6370449").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/05/03 09:57

S103	13	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic same (result\$1 or report\$3)) and transfer\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 10:02
S104	13	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic\$1 same (result\$1 or report\$3)) and transfer\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 10:05
S105	13	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic\$1 same (result\$1 or report\$3)) and transfer\$4 and diagnostic\$1	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 10:07

S106	6	(multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic\$1 same (result\$1 or report\$3)) and transfer\$4 and diagnostic\$1 and USB\$1	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 10:08
S107	2	("6687587").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/05/03 11:37
S108	2	("20030120395").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/05/03 11:38
S109	118	(multiple near3 processor\$1) and (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3)) and diagnostic\$1	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 12:02

S110	55	(multiple near3 processor\$1) and (automobile\$1 or vehicle\$1) and (((software or firmware) near2 (updat\$3 or upgrad\$3)) same diagnostic\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 12:03
S111	2	("6978198").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/05/03 12:39
S112	2	("5794164").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/05/03 12:42
S113	155	((multiple near3 processor\$1) same (automobile\$1 or car\$1 or vehicle\$1)) and (((software or firmware) near2 (updat\$3 or upgrad\$3 or install\$5))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 12:54

S114	5	((multiple near3 processor\$1 same (automobile\$1 or car\$1 or vehicle\$1)) and ((software or firmware) near2 (updat\$3 or upgrad\$3 or install\$5)) and (open architecture\$1))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 12:54
S115	10	((multiple near3 processor\$1 same (automobile\$1 or vehicle\$1)) and ((software or firmware) near2 (updat\$3 or upgrad\$3 or install\$5)) and (open interface\$1))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/05/03 12:55
S116	5	Shi-Jianying.IN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 10:32
S117	2	("5426585").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/09/30 10:36

S118	882	((vehicle near3 software) same (install\$5 or updat\$3))	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 10:49
S119	66	((vehicle near3 software) same (install\$5 or updat\$3) same processors)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 10:49
S120	2	((vehicle near3 software) same USB same (install\$5 or updat\$3) same processors)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 10:49
S121	12	((vehicle near3 software) same (install\$5 or updat\$3) same processors) and USB	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 10:50

S122	12	((vehicle near3 software) same (install\$5 or updat\$3) same processors) and USB and software	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 11:04
S123	12	((vehicle near3 software) same (install\$5 or updat\$3) same processors) and USB and software and (status or result or diagnostic)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 11:05
S124	66	((vehicle near3 software) same (install\$5 or updat\$3) same processors) and software	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 14:42
S125	82	((vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same processors) and software	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 15:11

S126	72	((vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same processors) and software and type\$1	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 15:12
S127	30	((vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same processors) and software and ((identif\$5 or determin\$3) near2 type\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 15:13
S128	0	Knight-Alexander.IN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 15:21
S129	3	Knight-Alexander-N\$.IN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 15:22

S130	1021	(vehicle near3 software) same (install\$5 or updat\$3 or load\$2) and (software or firmware or driver\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 17:40
S131	1021	(vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same (software or firmware or driver\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 17:40
S132	124	(vehicle software) same (install\$5 or updat\$3 or load \$2) same (software or firmware or driver\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 17:40
S133	11	(vehicle software) same processors same (install\$5 or updat\$3 or load\$2) same (software or firmware or driver\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 17:40

S134	6	(vehicle software) same processors same (install\$5 or updat\$3 or load\$2) same (software or firmware or driver\$1) and software and load\$3	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/09/30 17:45
S135	2	("6978198").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/11/10 17:01
S136	2	("20030163587").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/11/10 17:05
S137	2	("6832141").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/11/10 17:43

S138	173	(vehicle or automobile) near3 (software updat\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/11/10 17:46
S139	4	((vehicle or automobile) near3 (software updat\$3)) same status	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/11/10 17:47
S140	2	("20020035429").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/11/10 17:49
S141	2	("20040078119").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/11/10 17:52

S142	173	(vehicle or automobile) near3 (software updat\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/11/10 22:23
S143	2	("20080104583").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/11/10 22:24
S144	8	("7506309").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/11/10 23:26
S145	2	("6370449").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/05/11 16:00

S146	2	("6832141").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/05/11 16:08
S147	2	("6687587").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/05/11 16:09
S148	2354	(general motors) and (diagnostic or diagnosis)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2010/05/11 16:11
S149	343	(general motors) and ((diagnostic or diagnosis) same processor\$1)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2010/05/11 16:11

S150	343	(general motors) and ((diagnostic or diagnosis) same processors)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2010/05/11 16:11
S151	14	(general motors) and ((diagnostic or diagnosis) same processors same transfer\$3)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2010/05/11 16:12
S152	2	("6687587").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/05/11 16:18
S153	2	("20030120395").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/05/11 16:22

S154	2	("6978198").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/05/11 17:20
S155	2	("20100004853").PN.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2010/05/11 17:20

11/6/2010 5:22:53 PM

C:\Documents and Settings\bwang\My Documents\EAST Workspaces\2006\2006-Q4\\10701143.wsp